

# Oil Field Environmental Incident Summary

**Incident:** 20150423170546      **Date/Time of Notice:** 04/23/2015 17:05

**Responsible Party:** WIND RIVER OIL SERVICES

**Well Operator:** CONTINENTAL RESOURCES, INC.

**Well Name:** JAMESTOWN FEDERAL 2-17H

**Field Name:** BANKS

**Well File #:** 28202

**Date Incident:** 4/23/2015

**Time Incident:** 08:30

**Facility ID Number:**

**County:** MCKENZIE

**Twp:** 152

**Rng:** 99

**Sec:** 8

**Qtr:**

**Location Description:**

**Submitted By:** NATE STANHOPE

**Received By:**

**Contact Person:** LAURIE ROSE  
947 SOUTH 500 EAST, SUITE 100  
AMERICAN FORK, UT 84003

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Truck Overflow

**Release Contained in Dike:** Yes - On Facility Site

**Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	2	Barrels	2	Barrels		
Other						

**Description of Other Released Contaminant:**

N/A

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

N/A

**Areal Extent:**

***Potential Environmental Impacts:***

Location Soil

***Action Taken or Planned:***

Standing fluids were sucked up and returned to the tank. Solids were scraped up and disposed.

***Wastes Disposal Location:*** Bakken Western Services

***Agencies Involved:***

***Updates***

---

***Date:*** 4/24/2015    ***Status:*** Reviewed - Assigned to Other Agency

***Author:*** Stockdill, Scott

***Updated Oil Volume:***

***Updated Salt Water Volume:***

***Updated Other Volume:***

***Updated Other Contaminant***

***Notes:***

According to the incident summary, this spill impacted areas on location. NDIC retains oversight.